

ECLIMA - 121858 - COMPRESOR SANDEN SD6V12 CITROEN PV6 120MM 12V

6453QH 9800821980 9655191580 96551916 6453QG 9655191680 96551915 6453GZ / 6453JL / 6453JP / 6453KS / 6453LF / 6453LN / 6453LS / 9639078180 / 9646273880 / 9639078180 / 9646273380 / 9646273880 /

SD6V12, SD6V121430, SD6V121433, SD6V121433F, SD6V121438, SD6V121438F, SD6V121439, SD6V121449, SD6V121450, SD6V121459, SD6V121907, SD6V121908, SD6V121926, SD6V121927, SD6V121940, 0900K218, 11455, 130552, 130552R, 141433, 141433R, 1430, 1433, 1438, 1439, 1449, 1450, 1907, 1908, 1926, 1927, 1940, 1941, 20A1438A, 240514, 32227, 32227G, 3599771421376, 3599771421499, 4044455363910, 4045385062935, 510044, 5410909305185, 5415047002675, 550152, 55303929, 5530428S, 5704651055192, 5708114054920, 5708279141671, 6009K218, 6453FR, 6453JJ, 67104, 67197, 68104, 68197, 68197A, 68197O, 700510044, 811039015, 82D0156022CA, 8411141, 8433253030975, 8433253030999, 8435241017685, 851371N, 8600191, 8718042016713, 8718042137494, 8FK351134331, 8FK351134831, 8FK351316801, 8FK351322291, 8FK351322791, 920237, 945700, 97981, 98971A, 98981, 9931201, AC36149, ACP143, CNK218, DCK1177, E162218, F498981, FC0053, FC0071, K11133, K11455, KCN218, KPCN218 1201858, 1201863, 20A1438 850243N, 850686N, 851371N, 851679N 550152 141433, 141433R CNAK032, CNAK061, CNAK237, CNK032, CNK061, CNK218, CNK237, KPCN218 6453QF, 6453JJ, 6453XJ, 648714, 6453QE, 9800822280, 6453GZ, 6453QH, 6453KS, 6453QG, 6453JL, 6189509160, 6453LN, 9646273380, 6453GZ, 6453XP, 648722, 6453JL, 9684480480, 9684480480, 6453XQ, 9800822280, 6453XQ, 6453LN, 9655191680, E162218, 6453JP, 6453KS, 6453LF, 6453XQ, 6453LS, 6453LH, 6453QG, 6453JL, 6453XP, 648722, 6453QF, E162218, 6453JJ, 6453XJ, 6453LF, 6453QH, 6453JP, 6453FR, 6453LS, 9646273880, 6453JJ, 6453XQ, 9639078180, 6453JP, 9800822280, 9800822280, 648714, E162218, 648714, 6453LS, 9684480480, 006453FR, 6453KS, 6453LF, 6453LH, 648714, 6453QE, 6453LN, 6453QH, 6453JP, 6453XQ, 006453FR, 9639078180, 6453QG, 6453JL, 6453XP, 6453LH, 6453XJ, 6453KS, 6453GZ, 6453QE, 9655191580, 6453JL, 648714, 9646273380, 6453KS, E162218, E162218, 648722, 648722, 6453QE, 9800822280, 6189509160, 6453LF, 006453FR, 6453LH, 6453LN, 648722, 6453QF, 6453LS, 6453XJ, 6453KS, 648714, 6189509160, 9646273380, 6453QH, 6453JP, 6453XQ, 6453LN, 6453XP, 6453LF, 6453JJ, 6453QF, 9655191680, 6453JP, 648722, 9646273880, 6453LF, 9639078180, 9639078180, 6453QF, E162218, 6453FR, 6453LH, 6189509160, 6453LN, 6453LS, 9639078180, 6453QG, 6453QE, 6453XP, 6453LF, 648722, 6453FR, 96 FC0053 TSP0155334, TSP0155365, TSP0155404, TSP0155851, TSP0159334, TSP0159851 700510044 8600191 510044, 510045 AC35930, AC36149 11455 92020060, 92020206, 93020060 8FK351134331, 8FK351134831, 8FK351316801, 8FK351322291, 8FK351322791 K11455 CNK218 920120 100376, 130552, 1433, 46150, 6453FR, 811039015, 811040013, 8600191, CNK218, TSP0155334 ACP143 K11455 89053 32744 6189509160, 6453FR, 6453GZ, 6453JJ, 6453JL, 6453JP, 6453KS, 6453LF, 6453LG, 6453LH, 6453LN, 6453LS, 6453QE, 6453QF, 6453QG, 6453QH, 6453XJ, 6453XP, 648714, 648722, 9639038180, 9639078180, 9646273380, 9646273880, 9655191580, 9655191680, 9684480480, 9800822280, E162218 11455 97981, 98981, F497981, F498981 8600191 699356, 813689, 813814 0900K218, 0900K237 32227, 82D0156022CA 0928704244 SD6V12-1438F 6189501960

